

Exhibit 3: Photos of Restoration and Enhancement Work



**Shorebird and waterfowl use of brackish marsh - view to north**

---



**2.3 acre freshwater wetland – view to northeast**

Exhibit 3: Photos of Restoration and Enhancement Work



**6 acre freshwater wetland – view to the north east**



**6 acre freshwater wetland – view to the northeast**

Exhibit 3: Photos of Restoration and Enhancement Work



**6 acre freshwater wetland - view to north**



**Partially completed CDFG freshwater wetland area looking south west  
Shorebirds are loafing in the area between the levee and the new wetland area.**

Exhibit 3: Photos of Restoration and Enhancement Work



**Tide gate installation connecting levee to bayfront levee - view to north**



**CDFG culvert/tide gate installed**