

Exhibit 2: Project Photographs

Bloom Ranch, a



Bloom a, Photo displaying lower section of unnamed intermittent stream. In the proposal the plan includes restoring a cattle crossing (black arrow) and installing a livestock fence exclusion.



Bloom a, Close up of the planned lower livestock crossing to be repaired.

Exhibit 2: Project Photographs



Bloom a, Upstream view of unnamed stream to be fenced for livestock exclusion. The black arrow identifies where streambank grade stabilization repairs will occur.



Bloom a, Close up of planned streambank grade stabilization.

Exhibit 2: Project Photographs



Bloom a, Planned Stream Crossing repair #2.



Bloom a, Photo of planned headcut repair.

Exhibit 2: Project Photographs

Bloom Ranch, b



Bloom b, Streambank repair 1



Bloom b, Streambank repair 2.

Exhibit 2: Project Photographs

Lawson Ranch



Degraded stream crossing; planning to be repaired with culvert and grade stabilization.



Looking downstream just below the stream crossing, photo capturing the planned streambank and portion of stream to be fenced for livestock exclusion.

Exhibit 2: Project Photographs



Sandstone outcrop to be fenced for livestock exclusion.



Lower section, downstream of unnamed stream, planned streambank repair and livestock exclusion.