

Exhibit 4: Project Photos



Looking upstream into the twin culverts which currently obstruct passage of anadromous fish.

Exhibit 4: Project Photos



A typical pool upstream of the project site.