

Exhibit 2: Photos



Lower barrier #1: obsolete diversion dam



Middle impediment: low-flow road crossing to avocado grove

Exhibit 2: Photos



Upper barrier #2: main road crossing