

Exhibit 3. Site Photos



Daylighted reach of Woodacre Creek with riparian plantings at Woodacre Creek Improvement Club.

Exhibit 3. Site Photos



Salmon Crossing Sign Installed by Wilderness Way Environmental Program at Woodacre School.

Exhibit 3. Site Photos



Stream Simulation in bottomless arch culvert that replaced fish passage barrier just upstream of the confluence of Woodacre and San Geronimo Creeks

Exhibit 3. Site Photos



Looking upstream on San Geronimo Creek, just upstream of the confluence with Woodacre Creek.

### Exhibit 3. Site Photos



San Geronimo Valley Golf Course, just upstream of Roy's Pools. The creek is to the left of the picture. Note fence to keep golfers from entering creek to retrieve golf balls and causing bank erosion and loss of riparian vegetation.

Exhibit 3. Site Photos



Castro Road fish passage barrier at the base of the Arroyo Creek subwatershed. Confluence with San Geronimo Creek is approximately 200 ft downstream.