


Exhibit 2: Project Area



Map by Erin Everts, Topanga Anthropological Consultants

Map shows barriers to be removed as part of the steelhead restoration in Solstice Creek. All yellow and red barriers, which lie within NPS-owned land have been removed.