



Photo No 1: Site visit on 11-21-06. Large *Arundo donax* patch on left side of photo (east bank of Refugio Creek)



Photo No 2: Large *A. donax* stand in distance recently sprayed, near staging area.



Photo No 3: Crews using hand removal method of eradication on *A. donax*



Photo No 4: Cut and treated *A. donax* stockpiled on top of creek bank



Photo No 5: Crews chipping cut and treated *A. donax*. Chipped materials will be used on adjacent properties for mulch once deemed clean and clear of resprouts.



Photo No 6: California Red-Legged Frog seen in project area. Careful removal of exotic plant species under direction of approved biologist will enhance habitat for listed species.