

Exhibit 2. Site Photographs



Looking west at channelized Third Valley Creek downstream of footbridge.

Exhibit 2: Site Photos



View east at the mouth of Third Valley Creek and Tomales Bay.

Exhibit 2: Site Photos



Looking west at State Lands Commission Parcel, formerly wetlands.

Exhibit 2: Site Photos



Looking east at the State Lands Commission Parcel, which was formerly wetlands.
Channel B is on the left.

Exhibit 2: Site Photos



Looking north at Channel B where it flows across the beach. Persistent odor problems at this site are indicative of questionable water quality.