

Exhibit 2: Photos and Figures



Bright green lines around trails show closed trail restoration areas and green fencing along the Pond Trail. Access improvement locations are indicated by green circle with black dot.

Exhibit 2: Photos and Figures



Access B: Existing chain link fence at entrance to Sands beach. This fence will be replaced with a split-rail that looks like wood.




Example of Woodcrete fence that will replace chain link fence (note that the COPR fence will have 3 rails). Other examples of Woodcrete fence can be found at <http://www.designerconcrete.com/portfolio/rail/index.htm> .

Exhibit 2: Photos and Figures



Location of Woodcrete fence and gate on the north end of the Pond Trail.



Access D: Indicated by a white line. Location of new Woodcrete fence indicated by red line.

Exhibit 2: Photos and Figures



A group of volunteers and student interns planting along the Pond Trail under the WCB grant.



Example of roll-out boardwalk to be laid out in wet sections of the southern Pond Trail near Access C in very wet winters.