



Title/Notes:

Proposed Project Components and Existing Infrastructure

Figure:

3

Exhibit 2: Photos and Figures



Trails leading to Whistlestop Levee and Humming Bird Island



Title/Notes:

Whistlestop Lagoon Levee — Existing Conditions

Deformed 36-inch diameter culvert, looking west across Whistlestop levee. Cones mark the location of a large sink hole.

Figure:

4a

Exhibit 2: Photos and Figures

A



B



Title/Notes:

Whistlestop Lagoon Levee — Existing Conditions

Recently formed sinkholes on Whistlestop levee, November 2010. A. at 36-inch diameter culvert, and B. near the 24-inch diameter culvert.

Figure:

4b

Exhibit 2: Photos and Figures

A



B



Title/Notes:

Whistlestop Lagoon Levee — Existing Conditions

Whistlestop levee; A. flooded during a high tide event, and B. showing the deformed retaining wall on its south side.

Figure:

4c