

Exhibit 2. Site Photographs



Looking east at brackish marsh behind dike at White Slough Restoration Area.



Looking southwest at eroded dike at White Slough Restoration Area.

Exhibit 2. Site Photographs



High tide in Winter 2010 close to overtopping eroded dike around subsided wetlands at White Slough Unit of Humboldt Bay National Wildlife Refuge.



Non native brass buttons and *Agrostis* in former salt marsh at White Slough Unit.

Exhibit 2. Site Photographs



Dense, monotypic *Agrostis stolonifera* (above) and *Distichlis spicata* (below) in former salt marsh at Hookton Slough

