EXHIBIT 2: SITE PHOTOS AND RESTROOM DESIGN

Location 1: Cutoff Slough Failing Culvert Replacement

Location 2: Russ Creek Bridge Replacement

Location 3: Drainage Ditch Steel Bridge Placement



#1

Location 4: Vault Toilet Design