

Exhibit 4: Photos of Bridge Crossings and Trail Vegetation



Existing Typical Trail Section



Looking north at the Gannon Slough bridge location at low tide.



Looking north on the west side of the railroad berm at the washout at the Old Jacoby Creek bridge location



Looking west southwest at the Jacoby Creek bridge location at low tide